Approved For Release 2002/08/06: CIA-RDP80-00809A000700210091-3

	THE THE			
_	٠. ٨	CLASSIFICATION CONFIDENTIAL	25X1A	ILLEGIB
		SECURITY INFORMATION CENTRAL INTELLIGENCE AGENCY	REPORT, NO.	ILLEGIB
		INFORMATION FROM FOREIGN DOCUMENTS OR RADIO BROADCASTS	CD NO.	
	COUNTRY	USSR	DATE OF 25X1A	
	SUBJECT	Economic; Technological - Tire industry	INFORMATION 25X TA	
	HOW PUBLISHED	Daily newspapers	DATE DIST. 4/MAR 1953	
	WHERE PUBLISHED	USSR	NO. OF PAGES 3	
	DATE PUBLISHED	29 Jul - 25 Nov 1952	CHODI EMENT TO	
	LANGUAGE	Russian	SUPPLEMENT TO REPORT NO.	

THIS OCCUMENT CONTAINS INFORMATION APPECTING THE NATIONAL OFFICE OF THE UNITED STATES, BITAIN THE MEANING OF TITLE 18, SECTIONS 19, AND 784, OF THE U.S. CODE, AS AMENDED. 178 TRANSMISSION OR REVO-LATION OF 1TS CONTENTS TO OR RECEIFT BY AN UNAUTHORIZED PERSON 18 ASSISTED BY LES, THE REPRODUCTION OF THIS FORM 15 PROMISE TO.

THIS IS UNEVALUATED INFORMATION

SOURCE

Newspapers as indicated.

YEREVAN, LENINGRAD, MOSCOW TIRE PRODUCTION

SHIPS CLANT TIRES TO PROJECT -- Yerevan, Kommunist, 29 Jul 52

On 27 July 1952, the Yerevan Tire Plant shipped 915 of the 2,100 Gigant tires ordered by the Volga-Don Canal for the third quarter 1952.

EQUIPMENT SHORTAGE SLOWS OUTPUT -- Yerevan, Kommunist, 21 Sep 52

By installing two vulcanizers, the Yerevan Tire Plant could increase its production rate almost 30 percent.

PRODUCES FAULTY TIRES -- Yerevan, Kommunist, 30 Oct 52

In the summer of 1952, the Yerevan Tire Plant started receiving numerous complaints about its products. The defective tires were traced to defective cord. The Yerevan Tire Plant receives cord from Moscow, Yaroslavl', and Voronezh factories, but one fourth of its cord comes from the Kirovakan Cord Factory, and it was this cord that was causing the trouble.

The tire plant complained to the Kirovakan Cord Factory, but the quality of the cord grew worse, and 15,000 meters of defective cord had to be shipped back to Kirovakan. This cord had 120-130 points [indicating defects] checked off per 100 running meters compared to a norm of eight points. Ye. Voskanov, chief engineer, and other personnel of the Yerevan Tire Plant explained to workers of the Kirovakan Cord Factory that unequal thickness and grease spots on the and caused major defects in finished tires. Measures were taken to improve the work of production workers and inspectors at the cord plant and, as a result, defects were reduced to 10-12 points per 100 running meters by the middle of October. Recently, the Kirovakan plant has been preparing its equipment to make cord for Gigant tires. However, the plant still has much to do to eliminate remaining defects and to consolidate gains that have been made.

CLASSIFICATION . CONFIDENTIAL

25X1A

THE RESIDENCE THE PROPERTY OF THE PARTY OF T

	25X1A	ILLEGIB
TIAL		
skaya Pravůa, 18 Nov	52	
of the Design Divis d of the Technologic		
	e Engineering Econo- c Research Institute itute of the Tire	
repared was one of t	he most primitively	

CONFIDEN

TRACE GROWTH OF TIRE PLANT -- Leningred

In 1948, the Leningrad Tire Plant tire industry. P. I. Tikhomirov, chief modernizing the enterprise, with the aid Lensovet, the Polytechnic Institute ime mics Ins itute imeni V. M. Molotov, the for Synthetic Rubber VNIISK, the Scientific Rubber VNIISK, Industry, and other institutes.

The shop in which materials were p organized. Raw rubber was cut with hand knives, and granular materials were sifted by primitive devices. By the end of 1951, this shop was completely reorganized. Powerful vibrating screens have been set up to sift chemicals, and hydraulic shears are used to cut rubber. A special aggregate which performs all the operations involved in making treads has been set up. Productivity of the materials shop is now almost three times as great as before.

In the assembly shop, cord fabric was formerly rubber-coated one side at a time. Now a new four-shaft calender has been installed which rubber-coats both sides of the fabric simultaneously.

Formerly, most rejects and second-grade tires were caused by faulty vulcanization. Now, superheated water has replaced steam in the process, thus reducing vulcanizing time 20 percent.

The automobile and bicycle tube shop has been fully mechanized, and is now equipped with a tube machine, individual vulcanizers, etc.

All shops are equipped with conveyers for raw materials, and for semifabricated and finished products. In the vulcanization shop, for example, 300 tons of materials were formerly handled manually every day

More than 600 tons of materials, which were formerly moved manually, are now moved by 700 meters of conveyors, on transfer tables or by hoists.

A considerable number of control and measuring instruments have been installed to improve production processes. More than one third of all the tires produced by the plant are vulcanized in fully automatic machines.

In two shops, all vulcanization processes are fully automatic. The section which vulcanizes bicycle tires will soon be equipped with automatic equipment. The basic units for mixing rubber are now being made automatic, which should improve product quality.

The output of first-class products increased 16.4 percent in 1951, as comparea to 1948 and is now exceeding the plan figure. Rejects of finished products have been cut in half, and this improvement in quality was achieved in spite of a reduction in natural rubber content of the tires.

The plant has organized the output of new products such as tires with special treads for agricultural and garden tractors, tires for the Pobeda automobile. motorcycle tires, and proumatic clutches for petroleum drilling equipment. Mechanization and automatization of production processes has emabled the plant to fulfill its primary mission: to increase automotive and motorcycle tire output with the smallest possible expenditure. -- M. Parfenov, director of the Leningrad Tire Plant

- 2 -

CONFIDENTIAL

Approved For Release 2002/08/06: CIA-RDP80-00809A000700210091-3

CONFIDENTIAL	25X1A	ILLEGIB
INCREASE SYNTHETIC RUBBER CONTENT OF TIRES Moscow, Moskovsk	Taya Pravda, 25 Nov 52	
Engineers of the Moscow Tire Plant have designed a machine treads made entirely of synthetic rubber. Formerly, the treads after pressing, which made further processing necessary. The nonly turns out a better product, but also makes it possible to rubber, which is rapidly replacing natural rubber at the plant.	for pressing raw became deformed ew machine not	*
In 9 months of 1952, the plant has saved 338 tons of caouto square meters of fabric, and at the same time has reduced the conatural rubber 18.2 percent, compared to 1951 norms, by replacing the tic rubber.		;
However, there are still considerable losses due to rejects materials are wasted in preparing rubber mixtures. In the caler impregnation, drying, and other processes are also better the caler		

The Main Administration of the Tire Industry does not supply the plant with granulated carbon black, which makes it difficult to prepare mixtures properly, lowers quality, and raises production costs. -- N. Onufriyev, chief of the Planning Division, Moscow Tire Plant

impregnation, drying, and other processes are often carried out improperly. Insufficient precautions are taken to prevent overheating of rubber, thus lowering

- E N D -

the quality of output.